


**MODEL ITS-50R-120
 TRANSFER SWITCH**


MAXIMUM SERVICE
 120V 60Hz 1 Phase
 50A/Pole 2 Pole
 TIME DELAY 20-30 Seconds
 GENERAL LOADS

ELECTRICAL CONNECTIONS

TYPICAL GENERATOR/POWERCORD



TYPICAL INVERTER/ALTERNATE SOURCE



USE ANY KNOCKOUTS

WARNING

120 VOLT POWER SOURCE.
 MUST BE SECURED OFF BEFORE
 SERVICING. REFER SERVICE TO
 A QUALIFIED ELECTRICIAN.

NOTE

120 VOLT TRANSFER SWITCHES
 MAY NOT OPERATE IF POWER IS
 LOST ON ONE HOT LEG.

Use copper wire only
 75° C. minimum.